




Screen snap & Kit Parts List: Dual Channel LCD 500MHZ RF Power Meter With Data Logger

PM3A Sensor Silk:



PM3A Sensor Kit Parts List: DIP

Quantity	Check	Part Detail
2		8DIP IC Sockets
2		10uf Tan (C7, C8)
1		Sensor PTH PCB "FD-PM3A-03-DIP"
2		10pf Ceramic (C1, 12)
2		68 ohms (R13, 14)
12		100 ohms (R1 to R12)
2		470k (R15, 16)
2		BNC R/A Connector
1		D9F R/A Connector
4		10uh RFC (RFC1, 2, 3, 4)
8		0.1uf Poly (C2, 4, 5, 6, 9, 11, 13, 14)
2		0.1uf Tantalum (C3, 10)

Notes: AD8307 not included with Kit or Assembled

Dinesh Gajjar / 03rd August 2009

For more details, please visit Project Page: <http://www.foxdelta.com>